

1200 New Jersey Ave., SE Washington, D.C. 20590

In Reply Refer To: HSST-1/WZ-426

Mr. Henry A. Ross Plasticade 100 Howard Avenue, Des Plaines IL 60018 USA

Dear Mr. Ross:

This letter is in response to your February 26, 2021 request for the Federal Highway Administration (FHWA) to review a roadside safety device, hardware, or system for eligibility for reimbursement under the Federal-aid highway program. This FHWA letter of eligibility is assigned FHWA control number WZ-426 and is valid until a subsequent letter is issued by FHWA that expressly references this device.

## **Decision**

The following device is eligible within the length-of-need, with details provided in the form which is attached as an integral part of this letter:

• Plasticade SS620A Sign Stand with rollup sign at 84"

# **Scope of this Letter**

To be found eligible for Federal-aid funding, new roadside safety devices should meet the crash test and evaluation criteria contained in the American Association of State Highway and Transportation Officials' (AASHTO) Manual for Assessing Safety Hardware (MASH). However, the FHWA, the Department of Transportation, and the United States Government do not regulate the manufacture of roadside safety devices. Eligibility for reimbursement under the Federal-aid highway program does not establish approval, certification or endorsement of the device for any particular purpose or use.

This letter is not a determination by the FHWA, the Department of Transportation, or the United States Government that a vehicle crash involving the device will result in any particular outcome, nor is it a guarantee of the in-service performance of this device. Proper manufacturing, installation, and maintenance are required in order for this device to function as tested.

This finding of eligibility is limited to the crashworthiness of the system and does not cover other structural features, nor conformity with the Manual on Uniform Traffic Control Devices.

## **Eligibility for Reimbursement**

Based solely on a review of crash test results and certifications submitted by the manufacturer, and the crash test laboratory, FHWA agrees that the device described herein meets the crash test and evaluation criteria of the AASHTO's MASH. Therefore, the device is eligible for reimbursement under the Federal-aid highway program if installed under the range of tested conditions.

Name of system: Plasticade SS620A Sign Stand with rollup sign at 84"

Type of system: Work Zone Test Level: Test Level 3

Testing conducted by: Texas A&M Transportation Institute (TTI)

Date of request: February 26, 2021

FHWA concurs with the recommendation of the accredited crash testing laboratory on the attached form.

In accordance with FHWA's Memo "Federal-aid Reimbursement Eligibility Process for Safety Hardware Devices" dated November 12, 2015, FHWA will make note of any reported damage to a test vehicle's fuel tank, oil pan, or other feature that might serve as a surrogate of the fuel tank. AASHTO's MASH states "Although not a specific factor in assessing test results, integrity of a test vehicle's fuel tank is a potential concern. It is preferable that the fuel tank remains intact and not be punctured. Damage or rupture of the fuel tank, oil pan, or other feature that might serve as a surrogate of the fuel tank should be reported". A test report included in this submittal documenting Test 3-71at 90-degree angle states "there was a small cut in the transmission pan".

# **Full Description of the Eligible Device**

The device and supporting documentation, including reports of the crash tests or other testing done, videos of any crash testing, and/or drawings of the device, are described in the attached form.

# **Notice**

This eligibility letter is issued for the subject device as tested. Modifications made to the device are not covered by this letter. Any modifications to this device should be submitted to the user (i.e., state DOT) as per their requirements.

You are expected to supply potential users with sufficient information on design, installation and maintenance requirements to ensure proper performance.

You are expected to certify to potential users that the hardware furnished has the same chemistry, mechanical properties, and geometry as that submitted for review, and that it will meet the test and evaluation criteria of AASHTO's MASH.

Issuance of this letter does not convey property rights of any sort or any exclusive privilege. This letter is based on the premise that information and reports submitted by you are accurate and correct. We reserve the right to modify or revoke this letter if: (1) there are any inaccuracies in the information submitted in support of your request for this letter, (2) the qualification testing was flawed, (3) in-service performance or other information reveals safety problems, (4) the system is significantly different from the version that was crash tested, or (5) any other information indicates that the letter was issued in error or otherwise does not reflect full and complete information about the crashworthiness of the system.

# **Standard Provisions**

- To prevent misunderstanding by others, this letter of eligibility designated as FHWA
  control number WZ-426 shall not be reproduced except in full. This letter and the test
  documentation upon which it is based are public information. All such letters and
  documentation may be reviewed upon request.
- This letter shall not be construed as authorization or consent by the FHWA to use, manufacture, or sell any patented system for which the applicant is not the patent holder.
- This FHWA eligibility letter is not an expression of any Agency view, position, or determination of validity, scope, or ownership of any intellectual property rights to a specific device or design. Further, this letter does not impute any distribution or licensing rights to the requester. This FHWA eligibility letter determination is made based solely on the crash-testing information submitted by the requester. The FHWA reserves the right to review and revoke an earlier eligibility determination after receipt of subsequent information related to crash testing.

Sincerely,

Michael S. Griffith

Director, Office of Safety Technologies

Wichard & Tuffith

Office of Safety

**Enclosures** 

# Request for Federal Aid Reimbursement Eligibility of Highway Safety Hardware

	Date of Request:	February 26, 2021	<b>⊚</b> N	lew	○ Resubmission	
Submitter	Name:	Henry A. Ross	Henry A. Ross			
	Company:	Plasticade <sup>®</sup>				
	Address:	100 Howard Avenue, Des Plaines, IL 60018				
	Country:	U.S.A.				
		Michael S. Griffith, Director FHWA, Office of Safety Technologies				

I request the following devices be considered eligible for reimbursement under the Federal-aid highway program.

#### **Device & Testing Criterion -** Enter from right to left starting with Test Level

!-!-!

	System Type	Submission Type	Device Name / Variant	Testing Criterion	Test Level
- 1	,,,	C Engineering Analysis	Plasticade® SS620A Sign Stand with rollup sign at 84"	AASHTO MASH	TL3

By submitting this request for review and evaluation by the Federal Highway Administration, I certify that the product(s) was (were) tested in conformity with the AASHTO Manual for Assessing Safety Hardware and that the evaluation results meet the appropriate evaluation criteria in the MASH.

#### **Individual or Organization responsible for the product:**

Contact Name:	Henry A. Ross	Same as Submitter 🔀
Company Name:	Plasticade®	Same as Submitter 🔀
Address:	100 Howard Avenue, Des Plaines, IL 60018	Same as Submitter 🔀
Country:	U.S.A.	Same as Submitter 🔀

Enter below all disclosures of financial interests as required by the FHWA `Federal-Aid Reimbursement Eligibility Process for Safety Hardware Devices' document.

Texas A&M Transportation Institute (TTI) was contracted by Plasticade® to perform full-scale crash testing of the Plasticade® SS620A Sign Stand with rollup sign at 84". There are no shared financial interests in the Plasticade® SS620A Sign Stand with rollup signs by TTI, or between Plasticade® and TTI, other than the costs involved in the actual crash tests and reports for this submission to FHWA.

690900-PLC 19-21

# PRODUCT DESCRIPTION

New Hardware or     Significant Modification	Modification to Existing Hardware		
ORAFOL® vinyl rollup sign panel sign panel. Above the sign, three the stand was 14-ft 8 ¾-inches to	nd is a proprietary sign stand tested with a 48 inch squ . The sign panel was mounted at 84 inches from grade e conspicuity flags were mounted at the top of the star o the top of the flags. A 40-lb sand bag was placed on n stand weighed 60.8 lb (exclusive of the sand bags).	to the bottom of the nd. The overall height of	
	CRASH TESTING		
all of the critical and relevant cra	r affiliated with the testing laboratory, agrees in suppo sh tests for this device listed above were conducted to nined that no other crash tests are necessary to detern	meet the MASH test	
Engineer Name:	D. Lance Bullard, Jr., P.E.		
Engineer Signature:  D. Lance Bullard, Jr. Digitally signed by D. Lance Bullard, Jr. Date: 2021.02.26 13:21:59 -06'00'			
Address:	1254 Avenue A, Bldg 7091, Bryan, Texas 77807	Same as Submitter	
Country:	U.S.A.	Same as Submitter	

A brief description of each crash test and its result:

Required Test	Narrative	Evaluation
Number	Description	Results
3-70 (1100C)	3-70 MASH states that Test 3-70 for small vehicles is considered optional for workzone traffic control devices weighing less than 220 lb, because velocity changes during low-speed impacts with freestanding, lightweight features will be within acceptable limits. The Plasticade® SS620A Sign Stand weighed 60.8 lb (excluding the sand bags). Therefore, MASH Test 3-70 was not performed on this traffic control device. Non-critical, not conducted	Non-Critical, not conducted

MASH Test 3-71 involved an 1100C vehicle weighing 2420 lb ±55 lb impacting the traffic control device at an impact speed of 62 mi/h ±2.5 mi/h. Per MASH recommendations, the device was tested at critical impact angles (CIAs) of 90° ±1.5° and 0° ±1.5°.  The results of test 690900-PLP19 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOLe vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The test vehicle was traveling at an impact speed of 62.6 mi/h when it contacted the sign stand at an impact angle of 90°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 348 ft downstream of the point of impact and 7 ft toward the right of the centerline. No exterior crush to the vehicle or occupant compartment deformation was noted.  The results of test 690900-PLP19-21. In this test, a sign stand with a ORAFOLe vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to the left of centerline of the vehicle. There	
weighing 2420 lb ±55 lb impacting the traffic control device at an impact speed of 62 mi/h ±2.5 mi/h. Per MASH recommendations, the device was tested at critical impact angles (CIAs) of 90° ±1.5° and 0° ±1.5°.  The results of test 690900-PLP19 conducted on November 4, 2020 are found in TII Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL° vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The test vehicle was traveling at an impact speed of 62.6 mi/h when it contacted the sign stand at an impact angle of 90°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 348 ft downstream of the point of impact and 7 ft toward the right of the centerline. No exterior crush to the vehicle or occupant compartment deformation was noted.  The results of test 690900-PLP20 conducted on November 4, 2020 are found in TII Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL° vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch a 2-in	
traffic control device at an impact speed of 62 mi/h ±2.5 mi/h. Per MASH recommendations, the device was tested at critical impact angles (CIAs) of 90° ±1.5° and 0° ±1.5°.  The results of test 690900-PLP19 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL* vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The test vehicle was traveling at an impact speed of 62.6 mi/h when it contacted the sign stand at an impact angle of 90°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 348 ft downstream of the point of impact and 7 ft toward the right of the centerline. No exterior crush to the vehicle or occupant compartment deformation was noted.  The results of test 690900-PLP19-21. In this test, a sign stand with a ORAFOL* vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
62 mi/h ±2.5 mi/h. Per MASH recommendations, the device was tested at critical impact angles (CIAs) of 90° ±1.5° and 0° ±1.5°.  The results of test 690900-PLP19 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The test vehicle was traveling at an impact speed of 62.6 mi/h when it contacted the sign stand at an impact angle of 90°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 348 ft downstream of the point of impact and 7 ft toward the right of the centerline. No exterior crush to the vehicle or occupant compartment deformation was noted.  The results of test 690900-PLP20 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch x 2-inch area near the roof line and 16 inches to	
recommendations, the device was tested at critical impact angles (CIAs) of 90° ±1.5° and 0° ±1.5°.  The results of test 690900-PLP19 conducted on November 4, 2020 are found in TIT Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The test vehicle was traveling at an impact speed of 62.6 mi/h when it contacted the sign stand at an impact angle of 90°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 348 ft downstream of the point of impact and 7 ft toward the right of the centerline. No exterior crush to the vehicle or occupant compartment deformation was noted.  The results of test 690900-PLP20 conducted on November 4, 2020 are found in TIT Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle was traveling at an impact and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
critical impact angles (CIAs) of 90° ±1.5° and 0° ±1.5°.  The results of test 690900-PLP19 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL° vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The test vehicle was traveling at an impact speed of 62.6 mi/h when it contacted the sign stand at an impact angle of 90°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 348 ft downstream of the point of impact and 7 ft toward the right of the centerline. No exterior crush to the vehicle or occupant compartment deformation was noted.  The results of test 690900-PLP20 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
The results of test 690900-PLP19 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The test vehicle was traveling at an impact speed of 62.6 mi/h when it contacted the sign stand at an impact angle of 90°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 348 ft downstream of the point of impact and 7 ft toward the right of the centerline. No exterior crush to the vehicle or occupant compartment deformation was noted.  The results of test 690900-PLP20 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The test vehicle was traveling at an impact speed of 62.6 mi/h when it contacted the sign stand at an impact angle of 90°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 348 ft downstream of the point of impact and 7 ft toward the right of the centerline. No exterior crush to the vehicle or occupant compartment deformation was noted. The results of test 690900-PLP20 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2- inch area near the roof line and 16 inches to	
on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The test vehicle was traveling at an impact speed of 62.6 mi/h when it contacted the sign stand at an impact angle of 90°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 348 ft downstream of the point of impact and 7 ft toward the right of the centerline. No exterior crush to the vehicle or occupant compartment deformation was noted. The results of test 690900-PLP20 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2- inch area near the roof line and 16 inches to	
Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The test vehicle was traveling at an impact speed of 62.6 mi/h when it contacted the sign stand at an impact angle of 90°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 348 ft downstream of the point of impact and 7 ft toward the right of the centerline. No exterior crush to the vehicle or occupant compartment deformation was noted.  The results of test 690900-PLP20 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The test vehicle was traveling at an impact speed of 62.6 mi/h when it contacted the sign stand at an impact angle of 90°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 348 ft downstream of the point of impact and 7 ft toward the right of the centerline. No exterior crush to the vehicle or occupant compartment deformation was noted.  The results of test 690900-PLP20 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The test vehicle was traveling at an impact speed of 62.6 mi/h when it contacted the sign stand at an impact angle of 90°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 348 ft downstream of the point of impact and 7 ft toward the right of the centerline. No exterior crush to the vehicle or occupant compartment deformation was noted.  The results of test 690900-PLP20 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL* vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
grade to the bottom of sign was impacted. The test vehicle was traveling at an impact speed of 62.6 mi/h when it contacted the sign stand at an impact angle of 90°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 348 ft downstream of the point of impact and 7 ft toward the right of the centerline. No exterior crush to the vehicle or occupant compartment deformation was noted.  The results of test 690900-PLP20 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
The test vehicle was traveling at an impact speed of 62.6 mi/h when it contacted the sign stand at an impact angle of 90°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 348 ft downstream of the point of impact and 7 ft toward the right of the centerline. No exterior crush to the vehicle or occupant compartment deformation was noted.  The results of test 690900-PLP20 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
speed of 62.6 mi/h when it contacted the sign stand at an impact angle of 90°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 348 ft downstream of the point of impact and 7 ft toward the right of the centerline. No exterior crush to the vehicle or occupant compartment deformation was noted.  The results of test 690900-PLP20 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL° vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 348 ft downstream of the point of impact and 7 ft toward the right of the centerline. No exterior crush to the vehicle or occupant compartment deformation was noted.  The results of test 690900-PLP20 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
contact with the sign stand, and the vehicle came to rest 348 ft downstream of the point of impact and 7 ft toward the right of the centerline. No exterior crush to the vehicle or occupant compartment deformation was noted.  The results of test 690900-PLP20 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
came to rest 348 ft downstream of the point of impact and 7 ft toward the right of the centerline. No exterior crush to the vehicle or occupant compartment deformation was noted.  The results of test 690900-PLP20 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
of impact and 7 ft toward the right of the centerline. No exterior crush to the vehicle or occupant compartment deformation was noted.  The results of test 690900-PLP20 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
centerline. No exterior crush to the vehicle or occupant compartment deformation was noted.  The results of test 690900-PLP20 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
or occupant compartment deformation was noted.  The results of test 690900-PLP20 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
noted. The results of test 690900-PLP20 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0® to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2- inch area near the roof line and 16 inches to	
Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
grade to the bottom of sign was impacted. The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
The sign stand was aligned 0° to the test vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
vehicle. The test vehicle was traveling at an impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of $0^{\circ}$ . Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch $\times$ 2-inch area near the roof line and 16 inches to	
impact speed of 62.0 mi/h when it contacted the sign stand at an impact angle of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
of 0°. Brakes on the vehicle were applied after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
after loss of contact with the sign stand, and the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
the vehicle came to rest 323 ft downstream of and in line with the point of impact. The windshield was cracked over a 2-inch × 2-inch area near the roof line and 16 inches to	
of and in line with the point of impact. The windshield was cracked over a 2-inch $\times$ 2-inch area near the roof line and 16 inches to	
windshield was cracked over a 2-inch $\times$ 2-inch area near the roof line and 16 inches to	
inch area near the roof line and 16 inches to	
ן נוופ ופוג טו כפוזנפוןווופ טו מופ <b>יפוווגופ. ווופופ</b>	
were no holes or tears in the liner of the	
windshield. No fuel tank damage was	
observed. Maximum exterior crush to the	
vehicle was 2.0 inches in the front plane at bumper height. No occupant compartment	
deformation was observed.	
MASH does not require instrumentation of	
the vehicle when impacting lightweight,	
freestanding work zone traffic control	
devices weighing less than 220 lb, therefore	
the occupant risk factors were not	
calculated for this test. The Plasticade®	
SS620A Sign Stand weighed 60.8 lb	
(excluding the sand bags).  The device performed acceptably for MASH	
test 3-71 with an impact angle of 90° and 0°.	
costs / Time an impact drigit of you and o.	

MASH Test 3-72 involves a 2270P vehicle weighing 5000 lb  $\pm$ 110 lb impacting the traffic control device at an impact speed of 62 mi/h  $\pm$ 2.5 mi/h. Per MASH recommendations, the device was tested at critical impact angles (CIAs) of 90°  $\pm$ 1.5° and 0°  $\pm$ 1.5°.

The results of test 690900-PLP21 conducted on November 4, 2020 are found in TTI Test Report number 690900-PLP19-21. In this test, a sign stand with a ORAFOL® vinyl rollup sign panel mounted 84 inches from grade to the bottom of sign was impacted. The test vehicle was traveling at an impact speed of 64.0 mi/h when it contacted the first sign stand at an impact angle of 90°. The vehicle was traveling at an impact speed of 62.5 mi/h and impact angle of 0° when it contacted the second sign stand. Brakes on the vehicle were applied after loss of contact with the second sign stand, and the vehicle came to rest 303 ft downstream of and in line with the point of impact. The front bumper sustained two 1 inch deep deformations 13 inches to the right and left of centerline of the vehicle. The windshield was cracked and deformed 1.125 inches at the roof line 10 inches to the right of centerline of the vehicle. The windshield liner was intact with no holes or tears. No damage to the fuel tank was observed. Maximum exterior crush to the vehicle was 1.0 inch in the front plane and 13 inches to the right and left of the centerline of the vehicle at bumper height. Maximum occupant compartment deformation was 1.125 inches in the windshield. MASH does not require instrumentation of the vehicle when impacting lightweight, freestanding work zone traffic control devices weighing less than 220 lb, therefore the occupant risk factors were not calculated for this test. The Plasticade® SS620A Sign Stand weighed 60.8 lb (excluding the sand bags). The device performed acceptably for MASH test

3-72 with impact angles of 0° and 90°.

3-72 (2270P)

PASS

Full Scale Crash Testing was done in compliance with MASH by the following accredited crash test laboratory (cite the laboratory's accreditation status as noted in the crash test reports.):

Laboratory Name:	Texas A&M Transportation Institute		
Laboratory Signature:	Digitally signed by Darrell L. Kuhn 'Date: 2021.02.26 13:13:21 -06'00	DLKulm	
Address:	1254 Avenue A, Bldg 7091, Bryan, Texas 77807	Same as Submitter	
Country:	U.S.A	Same as Submitter	
Accreditation Certificate Number and Dates of current Accreditation period :	ISO 17025-2017 Laboratory A2LA Certificate Number: 2821.01 Valid To: April 30, 2021		

Submitter Signature\*: Henry A. Ross Date: 2021.03.02 10:40:00 -06:00

Submit Form
-------------


# **ATTACHMENTS**

#### Attach to this form:

- 1) Additional disclosures of related financial interest as indicated above.
- 2) A copy of the full test report, video, and a Test Data Summary Sheet for each test conducted in support of this request.
- 3) A drawing or drawings of the device(s) that conform to the Task Force-13 Drawing Specifications [Hardware Guide Drawing Standards]. For proprietary products, a single isometric line drawing is usually acceptable to illustrate the product, with detailed specifications, intended use, and contact information provided on the reverse. Additional drawings (not in TF-13 format) showing details that are relevant to understanding the dimensions and performance of the device should also be submitted to facilitate our review.


#### **FHWA Official Business Only:**

Eligibility Letter		
Number Date		Key Words



General Information		Test Vehicle	Post-Impact Trajectory	
Test Agency	Texas A&M Transportation Institute (TTI)	Type/Designation1100C	Stopping Distance	323 ft downstream
Test Standard Test No	MASH-2016 Test 3-71 at 0°	Make and Model 2014 Nissan Versa		and in line
TTI Test No	690900-PLP20	Curb 2461 lb	Maximum Test Debris Scatter	
Test Date	2020-11-04	Test Inertial 2452 lb	Sign Stand	323 ft downstream
Test Article		Dummy 165 lb	_	
Type	Work-Zone Traffic Control Device	Gross Static 2607 lb	Vehicle Damage	
Name	Plasticade® SS620A sign stand with	Impact Conditions	VDS	12FL1
	ORAFOL® vinyl rollup sign	Speed 62.0 mi/h	CDC	12FLEN1
Installation Height	84 inches to bottom of sign panel	Angle 0°	Max. Exterior Deformation	2.0 inches
Material or Key Elements	48 inch diamond-shaped rollup sign panel	Kinetic Energy 315 kip-ft	OCDI	FS0000000
-	held in place by a wing clamp sign holder	Exit Conditions	Max. Occupant Compartment	
	on 4-legged stand	Speed 60.2 mi/h	Deformation	None
Soil Type and Condition	Concrete pavement, dry; four 40-lb sand		Windshield Damage	Cracked 2-inch x
	bags		-	2-inch area

Figure 6.6. Summary of Results for *MASH-2016* Test 3-71 at 0 Degrees on Plasticade® SS620A Sign Stand with Rollup Sign at 84 inches.



	Texas A&M Transportation Institute (TTI)	Test Vehicle Type/Designation	Post-Impact Trajectory Stopping Distance	
TTI Test No	MASH-2016 Test 3-71 at 90° 690900-PLP19	Make and Model	Maximum Test Debris Scatter	7 ft right
Test Date Test Article	2020-11-04	Test Inertial	Sign Stand	348 ft downstream 7 ft right
Type	Work-Zone Traffic Control Device	Gross Static	Vehicle Damage	7 it right
	Plasticade® SS620A sign stand with ORAFOL® vinyl rollup sign	Impact Conditions Speed	VDS CDC	
Installation Height	84 inches to bottom of sign panel	Angle 90°	Max. Exterior Deformation	None
Material or Key Elements	48 inch diamond-shaped rollup sign panel held in place by a wing clamp sign holder	Kinetic Energy 319 kip-ft Exit Conditions	OCDI Max. Occupant Compartment	FS0000000
	on 4-legged stand	Speed 61.3 mi/h	Deformation	
Soil Type and Condition	Concrete pavement, dry; four 40-lb sand		Windshield Damage	none

Figure 5.6. Summary of Results for *MASH-2016* Test 3-71 at 90 Degrees on Plasticade® SS620A Sign Stand with Rollup Sign at 84 inches.

bags




Figure 7.6. Summary of Results for *MASH-2016* Test 3-72 at 90 degrees and 0 Degrees on Plasticade® SS620A Sign Stand with Rollup Sign at 84 inches.

Speed Sign Stand #1 ...... 62.5 mi/h

Speed Sign Stand #2 ...... 61.2 mi/h

Windshield Damage ...... Cracked 7-inch x

8-inch area

APPENDIX A. **DETAILS OF SS620A WITH ROLLUP SIGN AT 84 INCHES**