

OKANOGAN-WENATCHEE 2017 REPAIRS, PHASE 3

CONSTRUCTION NEWSLETTER

September 25, 2020

Project Number:

WA FS ERFO
2017(1)-23(3)

FHWA Contact:

Terry Hager
terry.hager@dot.gov
(360) 773-6341
610 East Fifth Street
Vancouver, WA 98661

Project Partner:

USFS - Okanogan-
Wenatchee National
Forest

Contractor:

Cates & Erb, Inc.
Omak, WA

Notice to Proceed:

March 23, 2020

Completion Date:

Fall 2020

Project Website: <https://highways.dot.gov/federal-lands/projects/wa/fs-erfo-2017-1-23-3>



U.S. Department
of Transportation

Federal Highway
Administration

Construction Activities

Work at Forest Service Road (FSR) 4010-050 MP 0.78 and MP 2.3 will continue next week. The 96-inch pipe culvert has been installed at MP 2.3 and the backfilling around the pipe culvert is underway.

Work on the 132-inch pipe culvert at FSR 4010-050 MP 0.78 has progressed forward with work primarily focusing on the inlet and outlet excavation areas. The last of the excavation work at MP 0.78 is expected to be completed in the week after next.

FSR 4010-050 will remain closed to public traffic until work at MP 0.78 and MP 2.3 is completed.

Work at FSR 4200/FSR 4200-400 MP 0.2 is expected to get underway next week. During this work FSR 4200-400 will remain closed to public traffic.

There will also be work on FSR 4200. During the work on FSR 4200, public traffic traveling on FSR 4200 near the junction with FSR 4200-400 will encounter delays. Public traffic will be allowed thru the area as work activities allow or during non-working periods. If possible, limit your travel through this area over the next few weeks.

Please, if the closed signs are up, stay out of the work area.

Also, use caution on roads nearby these sites, as there will be increased traffic related to work activities.



Road Impacts

- **Closed** - FSR 4200/4200-400 MP 0.2
 - Work expected to start next week
 - FSR 4200-400 - Closed at Jct. with FSR 4200
 - FSR 4200 - Expect delays
- **Closed** - FSR 4010-050 MP 0.78 & MP 2.3
 - Work underway



Above: Roadway Dip at FSR 4415-040 MP 0.4,

No risk of a plugged pipe culvert this winter.



Western Federal Lands Highway Division