

June 25, 2021

<u>Project Number:</u> ID FS ERFO 2017(2)-81(1) & ID FS ERFO 2018(1)-81(1)

FHWA Contact:

John Henderson john.henderson@dot.gov 360-839-3867

Project Partner:

US Forest Service Federal Highway Administration Western Federal Lands Highway Division

Contractor:

Ascorp, Inc.
DBA Debco Construction
217 College Ave #5
Orofino, ID 83544

Notice to Proceed: March 29, 2021

<u>Fixed Completion Date:</u> October 29, 2021



U.S. Department of Transportation

Federal Highway Administration

ID FS ERFO 2017(2)-81(1) & ID FS ERFO 2018(1)-81 (1) - Nez Perce Clearwater Repairs 2017 and 2018 Repairs Phase 1

Construction Activities & Upcoming Work

The Contractor is in full construction at Forest Service Road (FSR) 319 MP 1.6 (Fog Mountain), at FSR 443 MP 28 (Falls Point), at FSR 426 MP 0.5 and MP 2.7 (Bridge Creek) sites. Please remain alert to heavy truck traffic on Selway Road as well as Suttler Creek and Wilson Creek Roads, FSR 418, FSR 101, and all access roads to the repair locations.

<u>4TH of JULY weekend</u>: Contractor will not be working July 2-5, however construction equipment will remain at locations. Please observe all Road Closure barricades as they are there for our protection.


ROAD CLOSURES

- Fog Mountain Road NSFR 319, from the gate near the junction with Selway River Road 223
- Falls Point Road NSFR 443, from the gate near Selway Falls Campground
- Bridge Creek Road NSFR 426, closed for 6.3 miles beginning at the junction with NFSR 101
- The FSR 5503 Swan Creek road is currently closed for public safety.

The Nez Perce National Forest and the Clearwater National Forest will have a total of 17 Forest Service road repairs this year. All designated sites will be rebuilt and resurfaced where washouts have occurred. This may include new drainage, retaining walls, rock embankments, or reinforced soil slopes.

Project Website:

Western Federal Lands Highway Division




Project location is in the Nez Perce-Clearwater National Forest in the state of Idaho

locations for road repair within the **Nez Perce-Clearwater National Forest** Current work site locations are highlighted.

Project location maps showing 17

Source: FHWA



Source: FHWA

ID FS ERFO 2017(2)-81(1) & ID FS ERFO 2018(1)-81(1) - Nez Perce Clearwater Repairs 2017 and 2018 Repairs Phase 1

Photos Taken June 21-22, 2021



FSR 426 MP 0.5 Special Rock Embankment wall nearing completion

Source: FHWA

FSR 319 MP 1.6 MSE wall nearing completion



Source: FHWA